

Rick's Automotive
Facility Name

Attn:

Janet Doss

Approved Auto Repair
MAINTENANCE INSPECTION FORM

Vehicle Identification Number	VIN	Exterior Color	Exterior Color	Model Year	Model Year	Vehicle Type	Vehicle Type	Date Inspected

GENERAL INSPECTION				S	U
Wiper Blades	L	R	Rear		
Washer Fluid	Level	Pump			
Horn					
Mirrors	L	R	Inside		

V-BELTS & PULLEYS				S	U
All	WR	A/C	P/S	A/P	

SERPENTINE BELT				S	U
Bolt	Tensioner	Idler			

RECOMMENDATIONS

Replace all 4 Tires

Tires 272.00
 Valve Stem 18.00
 Diagnostic 18.00
 Static Tire Tax 2.00

Labor 58.00

Estimate \$368.00

LIGHTS				S	U
Dash Indicator Lights / Gauges					
Headlights	L	R	Lo Hi		
Park Lights	LF	RF	LR	RR	
Turn Signal	LF	RF	LR	RR	
Brake Lights	L	Center	R		
License	L	R			
Side Markers	LF	RF	LR	RR	
Back Up	L	R			

HOSES				S	U
Master	Inlet	Outlet	Dy-Pass		
Radiator		Upper	Lower		
Power Strg.	HP/Pass	Lo Pass			
Vacuum Hoses	Leaks	Cracks			
Fuel Hoses	Leaks	Cracks			

OTHER				S	U
Air Filter Duct	Clip/Housng	Air Hose			
PCV Valve	Hose	Valve			
Radiator	Cooling Fan(s)				

BATTERY				S	U
Tin	Tin	Hold Down	Cables		
Pass	Recharge/Rates		Fail		

LUBRICANTS / FLUIDS				S	U
Engine Oil	Level	Cond	Leaks		
Trans. Fluid	Level	Cond	Leaks		
P/Bleeding	Level	Cond	Leaks		
Anti-Freeze	Level	Cond	Leaks		
Brake Fluid	Level	Cond	P R		

BRAKE INSPECTION				S	U
Rotors / Drums	(Inch / mm)			S	U
Front	Min/Max	Actual			
LF					
RF					
Rotors / Drums	(Inch / mm)			S	U
Front	Min/Max	Actual			
LR				LR	
RR				RR	

PADS / SHOES				S	U
		Min	Actual		
LF					
RF					

TIRES					S	U
Tire Pressure						
LF	RF	LR	RR	Spare		

Tread Depth (min 2/32)					S	U
LF	RF	LR	RR	Spare		

I have reviewed this Maintenance Inspection Report and understand that it is given to show the condition of the vehicle at the time of its inspection and evaluation only, and is made without any representation, guarantee or warranty of any kind, either expressed or implied or arising by operation of law. I acknowledge that no action has been taken to correct any condition reported, and that the safe operation and maintenance of the vehicle following the inspection is my sole responsibility. I also understand that the results recorded above may be used in the collection of statistics relative to vehicle maintenance, and that copies of this report may be given to program sponsors upon request.

I also acknowledge that this Maintenance Inspection Report is made solely by the facility performing the inspection, which is an independent business, and that neither AAA nor Automobile Club of Missouri certify, guarantee, warrant or make any representations concerning the quality, accuracy or completeness of this Maintenance Inspection Report, the inspection itself or any repairs.

Motorist's Signature
 Copyright ©2012 Automobile Club of Missouri. All Rights Reserved.

Date

08/12/2013 0041269